

Potential Failure Mode and Effects Analysis (Design FMEA)

Design Responsibility: Workgroup

Key Date: October 2000

FMEA Number: MIT 1

Page 1 of 3

Prepared by: M.Andrew

FMEA Date (Orig.): 2000.02.16 (Rev.): 2010.02.16

___Subsystem

_X_Component: Connector System

Model Year/Vehicle(s): / 42 VOLT SYS

Core Team: Refer to workgroup list

Ttem Function	Potential Failure Mode	Potential Effect(s) of Failure	C S 1 e a v s s	Cause(s)/ Mechanism(s) Failure	0 c u r	Controls	D e t e c	P.	Recommended Action(s)	Responsibility & Target Completion Date	Action Actions Taken	. S	s u i	D e	R. P.
electrical current with maximum voltage drop of (50mV), for	Excessive voltage drop	Overheating Reduced voltage to loads	8	decreased normal force partially backed-out connector		end-of-line check test									
up to xxx sec. over and ambient temperature range of -40C to 80C.				partially backed-out terminal											
Voltage drop spec.				loss of asparities(terminal interface)											
end-of-conditioning status, including				Environmental conditions											
Meet stds.for underhood environment				material properties											
(corrosion resistance)	system not electrically connected	open circuit	7	excessive mating force											
Must withstand SAEJ537 spec.for vibration Must satisfy thermal cycling spec.				inadequate connector latch											
	terminal not connected	open circuit	7	terminal partially seated											
				damaged terminal improper terminal											-
				orientation											
				excessive mating force										-	-
maintains mechanical integrity	doesn't support cable load	open, short, or intermittent circuit, or overheating		inadequate material selection(housing or terminal)											
				inadequate strain relief											
	unmated connectors	Open circuit overheating Reduced voltage to loads		partially backed-out connector											
				partially backed-out terminal											



__Subsystem

Potential Failure Mode and Effects Analysis (Design FMEA)

Design Responsibility: Workgroup _X_Component: Connector System

Model Year/Vehicle(s): / 42 VOLT SYS Key Date: October 2000

Core Team: Refer to workgroup list

FMEA Number: MIT 1

Page 2 of 3

Registered to: FMEAplus User

Prepared by: M.Andrew

FMEA Date (Orig.): 2000.02.16 (Rev.): 2010.02.16

Item	Potential Failure Mode	Potential Effect(s) of Failure	C	Potential	0		D e I t I e I			Responsibility & Target Completion Date	Action Results					
Function			S 1 e a v s s	Mechanism(s) Failure	c u r	Design Controls		P.	Recommended Action(s)		Actions Taken	е	c	D R e P t N		
				loss of asparities(terminal interface)												
shorting of positive		Excessive current draw Overheating		Design Dependent - to be identified for each design.												
	Increased voltage drop	Overheating Excessive voltage drop to load		loss of asparities(terminal interface)												
amps for a minimum of 50 cycles)				decreased normal forc												
er so eyerer,	reduced mechanical retention force	open, short or intermittent circuit		broken connector latch												
				inadequate connector latch												
	unmate force is excessive	Can't disconnect battery Permanent damage to the system		Cold welds at the interface												
				Corrosion												
				Mechanical latch failure												
				Mechanical distortion of separable interface												
Prevent reverse connections	Reverse connections are made	Damage to vehicle electrical system. Damage to connection		Inadequate polarization or indexing												
Prevent 12 volt to 36 volt connections	Wrong connections are made	Damage to vehicle electrical system.		Inadequate indexing												
36 VOIC COMMECTIONS	are made	Damage to connection Battery damage		Allows for alligator style jumper cable attachment												
Prevent connection to different battery chemistry technology(indexing required at positive only)		Damage to battery		Inadequate indexing												

Printed on: 2000.03.01 12:47:36

Produced by FMEAplus for Windows v4.1



Potential Failure Mode and Effects Analysis (Design FMEA)

Design Responsibility: Workgroup

Key Date: October 2000

FMEA Number: MIT 1

Page 3 of 3

Prepared by: M.Andrew

FMEA Date (Orig.): 2000.02.16 (Rev.): 2010.02.16

___Subsystem

_X_Component: Connector System

Model Year/Vehicle(s): / 42 VOLT SYS

Core Team: Refer to workgroup list

Item Function	Potential Failure Mode	Effect(s) of	S 1 e a v s	Cause(s)/ Mechanism(s) Failure	O c c u r	Current Design Controls	D e R. t P. e N. c	Recommended Action(s)	Responsibility & Target Completion Date	Action F Actions Taken	s e	0	D R. e P. t N.
Prevent customers access with standard jumper cables on the connection system		Damage to the vehicle electrical system Damage to battery Damage to connector		Allows for alligator style jumper cable attachmen									
Disconnect under XX electical load	Damage to connection system	Oveheating warping excessive spark permanent damage to the connection system		excessive arcing - impact will be design dependent									
	requires more than 75 N to mate	Cannot mate connection open circuit Partially mated Ergonomic concerns		Out of spec on mating alignment assurance									
				damaged terminals									
				improper terminal orientation									
				damaged housing									
				Contamination									
75 N maximum unmating force(minimum locking strength of 110 N) USCAR 5.4.2.4	requires more than 75 N unmating force			damaged terminals									
				improper terminal orientation									
				damaged housing									
				Contamination/corrosion									
	Less than 110 N locking strength	Terminal latch disengages before the connector unmates		Inadequate terminal retention feature									
				Improper material									
maintain stable cable routing orientation	cable out of desired position	damaged battery cable		Inadequate mechanical positioning feature									

Printed on: 2000.03.01 12:47:36

Produced by FMEAplus for Windows v4.1