

## **PFMEA Common Mistakes**

- 1. Applying thresholds.
- 2. Not recognizing all potential failures.
- 3. Failure to properly identify the customer.
- 4. Misapplication of ranking scales.
- 5. Confusing Failure Modes with Effects or Failure Modes with Causes.
- 6. Failure to develop Recommended Actions or Recommended Actions that are neither actionable nor executable.
- 7. Applying Occurrence and Detection too optimistically.
- 8. Failure to accurately describe the Process Function Requirement.
- 9. Failure to consider the "Potential" nature of Failure, Effect, Cause.
- 10. Allowing the PFMEA to turn into a design review.

